APD NEEDS THE FOLLOWING ATTAL AS PER TONI POOL: POPE STATE BOND WITH

COPY OF COVERLITH

TO THIS AGENCY VA- CONSENT OF LEASE MICH HOLDER - SEC 17 TO 3/9/83 WEST OF DAILL SITE. Mor 3-7-83 asked Jisa for water night and other environmental for ROCC neview, should be appreciate review become necessary. (No bond yet) spring 3



(Other instructions on reverse side)

4


STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS, AND MINING

5. Lease Designation and Serial No.

				ML-29559	
APPLICATION	FOR PERMIT TO	O DRILL, DEEF	EN, OR PLUG	BACK 6. If Indian, Allottee or	Tribe Name
a. Type of Work					
DRILL	. 🛚	DEEPEN 🗌	PLUG B	ACK 7. Unit Agreement Name)
b. Type of Well Oil 🔽 / Gas			Single M	ultiple 8. Farm or Lease Name	
Oil Gas Well Well Well 2. Name of Operator	1 Other			ne —	
Pool Energy	Corporation	-	C=2 0001	Range Cree	<u> </u>
6. Address of Operator	COLPOLACION	303-	573-0091		
309 Guaranty	Bank Bldg	817-17+h S	t Denver	#1-16 CO 8020 ^{20. Field and Pool, or W}	ildcat
 Location of Well (Report 	t location clearly and in a	ccordance with any Sta	te requirements.*)	Wildcat	
At surface	' FNL & 538'		,	11. Sec., T., R., M., or	Blk.
At proposed prod. zone	-11 -2 u, 000	- 112		and Survey or Area Section 16	
	NW/NW, Sect	ion 16		T17S-R14E	•
4. Distance in miles and o	lirection from nearest town	n or post office*			13. State
Located 33 m	iles northwe	st of Price	, Utah.	Emergy	UT
 Distance from proposed location to nearest 	*		No. of acres in lease	17. No. of acres assigned to this well	
property or lease line, : (Also to nearest drlg. line)	ft. ne, if any) 364	1	834.74	Non-spaced	3.
18. Distance from proposed to nearest well, drilling	location*	19.	Proposed depth	20. Rotary or cable tools	
or applied for, on this l	ease, ft. non	e	8500 '	Rotary	
21. Elevations (Show whether	, , , ,			22. Approx. date work	will start*
4879' Gr.				April 1,	1983
23.	I	PROPOSED CASING AN	ND CEMENTING PROGRA	AM	
Size of Hole	Size of Casing	Weight per Foot	Setting Depth	Quantity of Cement	
23"	20"	Conductor	60'	Cement to suri	face
12-1/4"	9-5/8"	36#	600 '	225 sx. cement	
7-7/8"	5-1/2"	20#	8500'	200' above pay	zone
Mississippia completed. State of Uta	n formation. If dry, the h regulation	If productively well will be s.	tive, casing e plugged and	A 17	ne well the
reventer program, if any.	s to dim or deepen directi	onany, give pertinent (ara on subsurface logator	and true vertical dept	ns. Give blowou
Signed Sea	- Y Y	lla Title	BY: Consultant	7 Date 3-1	L - 83
(This space for Federal	or State office use)				
Permit No			Approval Date		
Approved byConditions of approval,	if any:	Title		Date	·····



R. 14 F.



Powers Elevation of Denver, Colorado has in accordance with a request from Tom Pool for POOL ENERGY CORP.

determined the location of RANGE CREEK #1-16

to be 538' FWL & 956' FNL Range 14 East, Salt Lake

Township 17 South Section 16

T. 175.

JAMES E.

Meridian

Emery County, Utah

I hereby certify that this plat is an accurate representation of a correct survey showing the location of

Date: FER. 21, 1983

Licensed Land Surveyor No. Cols Zanaminimin



March 1, 1983

State of Utah Division of Oil, Gas & Mining 4241 State Office Building Salt Lake City, UT 84114

RE: Pool Energy Corporation #1-16 Range Creek 956' FNL & 538' FWL Section 16, T17S-R14E Emery County, Utah MAR 0 4 1983

DIVISION OF GAS & MINING

Gentlemen:

Pool Energy Corporation proposes to drill a well at the above-mentioned location.

We realize that this location is a non-standard location, in accordance with the spacing rules for the State of Utah. This location was picked due to seismic work which was done in the immediate area.

Pool Energy Corporation is the lease holder of all of Section 16, T17S-R14E. Therefore, no other lease holders will be affected by the drilling of the above-proposed well.

We, therefore, request your permission to drill this well at a non-standard location.

Sincerely,

PERMITCO

Lisa L. Green Consultant for

Pool Energy Corporation

LIG/tjb

Enclosure

cc: Pool Energy Corporation

•	•	
OPERATOR POOL ENERGY CORP		DATE 3-7-83
WELL NAME RANGE CAEEK 1-16		
SEC NW NW XG T 175	R 14E COUNTY	EMERY
43-015-30161		STATE
API/NUMBER	· TY	TPE OF LEASE
POSTING CHECK OFF:		
INDEX	HL	
NID	PI	
MAP		
PROCESSING COMMENTS: / jp oil welks	within 1000	
0.40.		
JP		
APPROVAL LETTER:		
SPACING: A-3 UNIT	c-3	CAUSE NO. & DATE
4		
c-3-b	C-3	3-c
SPECIAL LANGUAGE:		1 to 1 down to
SPECIAL LANGUAGE: Approval condition	al upon install	allon of anichale
soreguipment; discr	extion of water	source onid water
rights; and submitte	al of an approve	ed plan to protect the
emironment hom sole	ution which m	whit be coused hom
mud and water impour	ndment, human	waste, and garbage
or trash.		

	RECONCILE WELL NAME AND LOCATION ON APD AGAINST SAME DATA ON PLAT MAP.
<u></u>	AUTHENTICATE LEASE AND OPERATOR INFORMATION
	VERIFY ADEQUATE AND PROPER BONDING NEEDS BOND 3.18
	AUTHENTICATE IF SITE IS IN A NAMED FIELD, ETC.
	APPLY SPACING CONSIDERATION
	ORDER NO
	UNIT
	c-3-b
	c-3-c
	OUTSTANDING OR OVERDUE REPORTS FOR OTHER WELLS OF THE OPERATOR.
V	IF POTASH DESIGNATED AREA, SPECIAL LANGUAGE ON APPROVAL LETTER
10/	OIL SHALE

•



A Petroleum Permitting Company

March 7, 1983

Yellowstone Resources 1726 Champa, Ste. 300 Denver, CO 80202

ATTN: Mr. Tom St. John

Vice President of Land

Pool Energy Corporation RE:

Range Creek #1-16 956' FNL & 538' FWL Section 16, T17S-R14E Emery County, Utah

Dear Mr. St. John:

Pool Energy Corporation proposes to drill a well at the above-mentioned location. Our records indicate you are the leaseholder of the NE/NE of Section 17, T17S-R14E, Emery County, Utah.

If you have no objections to the drilling of this well, please indicate by signing at the space provided below. Thank you for your cooperation regarding this matter.

Sincerely,

PERMITCO

Lisa L. Green Consultant for

Pool Energy Corporation

LLG/tjb

State of Utah cc:

Pool Energy Corporation

I, Tom St. John, Vice President of Land for Yellowstone Resources, have been notified of Pool Energy Corporation's intent to drill a well at the above mentioned location and have no objections to the drilling of this well.

Vice Pres. of Land

1020 Fifteenth Street Brooks Towers, Suite 22-E Denver, Colorado 80202 (303) 595-4051



A Petroleum Permitting Company

March 7, 1983

State of Utah Division of Oil, Gas & Mining 4241 State Office Building Salt Lake City, UT 84114

ATTN: Mr. Ron Firth

RE: Pool Energy Corporation

Range Creek #1-16 956' FNL & 538' FWL Section 16, T17S-R14E Emery County, Utah MAR 0 9 1983

DIVISION OF GAS & MINING

Dear Ron:

As per our telephone conversation, enclosed please find a letter from Mr. Tom St. John of Yellowstone Resources, the leaseholder of the NE/NE of Section 17, T17S-R14E, Emery County, Utah. Yellowstone Resources is the only leaseholder within a 660' radius of the proposed location who will be affected by the drilling of this well.

Should you need anything further to process the previously submitted permit, please feel free to contact the undersigned.

Sincerely,

PERMITCO

Lisa L. Green Consultant for

Pool Energy Corporation

Sisa S. Shee

LLG/tjb

Enclosure

cc: Pool Energy Corporation



A Petroleum Permitting Company

March 8, 1983

State of Utah Division of Oil, Gas & Mining 4241 State Office Building Salt Lake City, UT 84114

ATTN: Mr. Ron Firth

RE: Pool Energy Corporation

Range Creek #1-16
NW/NW Section 16

T17S-R14E

Emery County, Utah

MEGELVEU MAR 1 0 1983

DIVISION OF OIL, GAS & MINING

Dear Ron:

As per our telephone conversation of this date, please find enclosed a copy of the access map and archeological study for the subject location.

If you should have any questions, please contact me at your convenience. Thank you for your cooperation regarding this matter.

Sincerely,

PERMITCO


Lisa L. Green Consultant for

Pool Energy Corporation

LLG/tjb

Enclosures (2)

cc: Pool Energy Corporation





La Plata Archeological Consultants, Inc.

P.O. Box 783 Dolores, Colorado 81323

303-882-4933

March 2, 1983

Mr. Blaine Miller Area Archeologist Bureau of Land Management P.O. Box AB Price, Utah 84501

Mr. Miller:

Please find enclosed the archeological survey report for Pool Energy Corporation's Ranger Creek #1-16 well pad and access road, located in Emery County, Utah. The well pad is located on State owned lands, however, the access road crosses BLM administered properties. No cultural resources were located and archeological clearance is recommended.

Sincerely,

Patrick L. Harden

President

Distribution:


BLM - Salt Lake City Moab

Utah State Historical Society - antiquities Section USGS - Oil & Gas Branch, Salt Lake City

Permitco

Pool Energy Corp.

PLH/rjs



DIVISION OF OIL GAS & MINING

AN ARCHEOLOGICAL SURVEY OF POOLE ENERGY CORPORATION'S RANGER CREEK #1-16 WELL PAD AND ACCESS ROAD EMERY COUNTY, UTAH

LAC REPORT 8309

BY Patrick L. Harden

LA PLATA ARCHEOLOGICAL CONSULTANTS, INC.
P.O. BOX 783
DOLORES, COLORADO 81323
303-882-4933

March 2, 1983

Federal Antiquities Permit 83-AZ/CO/UT/NM-006 State Antiquities Permit #837

Prepared For:
Poole Energy Corporation
Suite 309
817 17th Street
Denver, Colorado 80202

ABSTRACT

An archeological survey of Poole Energy Corporation's Range Creek #1-16 well pad and access road was conducted by personnel of La Plata Archeological Consultants on February 26, 1983. The well pad is located on lands owned by the state of Utah, with the access route crossing both State lands and those administered by the Bureau of Land Management - Price Resource Area. An area 600 X 600 feet surrounding the well pad center stake, and a 20 meter (66') wide corridor along the ca. 5000 feet of access road were archeologically surveyed. No cultural resources were noted in the project area. Archeological clearance is recommended for this project.

INTRODUCTION

At the request of Ms. Lisa Green, acting permit agent for Poole Energy Corporation, an archeological survey of the access route for the Range Creek #1-16 well pad was conducted by Patrick Harden of La Plata Archeological Consultants, Dolores, Colorado on February 26, 1983. It was decided that the well pad should also be surveyed since only a small amount of extra time would be required for the investigation. Although archeological inventory for developmental projects located on State lands is usually not specifically required (at this time), such investigations are prudent due to the fact that developmental companies are liable in the event that cultural resources are encountered during construction activities.

The proposed project includes the construction of a single well pad ca. 275 X 300 feet in size, and improvements to an existing field road for approximately 5000 feet. The access road will join highway 6 to the southwest of the well pad.


The well pad is located in the NW¼, NW¼, Section 16, T17S, R14E; and the access road in the NE¼ and SW¼ of Section 17; Emery County, Utah. The area is included on the Woodside, Utah 15' series topographic map (1949).

PHYSIOGRAPHY AND ENVIRONMENT

The project area is located from two to three miles west of the Book Cliffs, and ca. four miles south of the geologic feature known as The Cove. The Price River is located three miles southwest. The area is $5\frac{1}{2}$ miles north of the tiny town of Woodside and about 32 miles southeast of Price, Utah.

The terrain is characterized by large pediments dipping southerly from the Book Cliffs. Relatively open level areas are interspersed by low ridges and isolated knolls. Erosion has created a rather stark landscape in the area. Marsh Flat Wash drains the vicinity, and tributary arroyos are, in places, deeply entrenched in the project area. Large fans formed from colluvium eroding from the Book Cliffs are located to the east of the project area. Sediments consist of gravely to rocky sandy silt and clay, with isolated clay and shale knolls.

Vegetation is a desert shrub community, with mat saltbush, greasewood, prickley pear, bunch grass, shadscale, and rabbit-



brush represented. Generally, vegetation is sparse and stunted, attributed to both the nature of the sediments and low precipitation.

Water sources are restricted to the intermittent arroyos in the immediate area, and the perennial Price River located three miles to the southwest.

Elevations range between 4800 and 4900 feet.

EXAMINATION PROCEDURES

Prior to the initiation of field work a file and literature review was conducted via telephone with Mr. Blaine Miller, Price River Resource Area archeologist. The results of this review indicated that none of the area had been previously inventoried for cultural resources, and no sites or National Register properties were in the project area. A Class II sample survey was conducted in the general Price River area, but no sample quadrats were located near the Poole Energy project (Hauck 1979).

On-the-ground survey was conducted by the single investigator systematically walking over the well pad area via transects spaced at 15 meter intervals. An area 600 X 600' surrounding the well pad center stake was investigated. The ca. 5000' of access road was walked via a single sinuous transect, effectively covering a 20m wide corridor. Both the well pad and access route were flagged prior to the investigations. The access route follows an existing field road. The field

road crosses Marsh Flat Wash at an angle, so an area 150 X 150' was surveyed in this locale in order to allow some modifications in road placement to facilitate equipment access. Additional flagging was placed along the access route during the archeological survey.

SURVEY RESULTS

No cultural resources were found in the project area.

The nature of the sediments makes the possibility of buried cultural deposits being present highly unlikely.

CONCLUSION

The archeological survey of Poole Energy Corporation's Range Creek #1-16 well pad and access road was conducted by Patrick Harden of La Plata Archeological Consultants on February 26, 1983. An area 600 X 600' surrounding the well pad center stake, and a 20 meter (66') wide corridor along the access route were investigated. The well pad is located on lands owned by the state of Utah, and the access route is on lands administered by the Bureau of Land Management - Price River Resource Area. No cultural resources were found and archeological clearance is recommended for this project.

REFERENCE CITED

Hauck, F.R.

1979 Cultural Resource Evaluation in Central Utah

1977. Cultural Resource Series No. 3. Bureau
of Land Management, Salt Lake City.



March 16, 1983

Division of State Lands and Forestry 3100 State Office Building Salt Lake City, Utah 84114

Attention: Mr. Donald G. Prince

Re: Range Creek #1-16 956' FNL & 538' FWL Section 16-T17S-R14E Emery County, Utah Lease ML 29559

Gentlemen:

We are enclosing a Designation of Operator form designating Pool Energy Corporation as operator and lease bond for lease ML 29559.

Please advise us if you require any further information in order to process our Application for Permit to Drill at the referenced location.

Thank you for your assistance.

Very truly yours,

Fred W. Pool II

FWP/mr

Encs.

cc: Utah Division of Oil, Gas and Mining

4241 State Office Building Salt Lake City, Utah 84114 Attention: Mr. Norm Stout Holding File



DIVISION OF OIL, GAS & MINING

DESIGNATION OF OFERATOR

The undersigned is, on the records of the Department of Natural Resources, Division of State Lands, holder of lease, ML 29559

and hereby designates

NAME:

POOL ENERGY CORPORATION

ADDRESS:

309 Guaranty Bank Building

817 17th Street

Denver, Colorado 80202

as his operator and local agent, with full authority to act in his behalf in complying with the terms of the lease and regulations applicable thereto and on whom the Director of the Division of State Lands or his representative may serve written or oral instructions in securing compliance with the Rules and Regulations Governing the Issuance of Mineral Leases with respect to (describe acreage to which this designation is applicable):

> Township 17 South, Range 14 East, SLM Section 16: NW

Emery County, Utah

It is understood that this designation of operator does not relieve the lessee of responsibility for compliance with the terms of the lease and the Rules and Regulations. It is also understood that this designation of operator does not constitute an assignment of any interest in the lease.

In case of default on the part of the designated operator, the lessee will make full and prompt compliance with all regulations, lease terms, or orders of the Director, Division of State Lands or his representative.

The lessee agrees promptly to notify the Division of State Lands of any change in the designated operator.

General Partner

309 Guaranty Bank Building, 817 17th Street Denver, Colorado 80202 (Address)

Pool Energy Corporation 309 Guaranty Bank Bldg. 817 - 17th Street Denver, Colorado 80202

> RE: Well No. Range Creek 1-16 NWNW Sec. 16, T.17S, R.14E 956' FNL, 538' FWL Emery County, Utah

11

Gentlemen:

Insofar as this office is concerned, approval to drill the above referred to oil well on said unorthodox location is hereby granted in accordance with Rule C-3(c), General Rules and Regulations and Rules of Practice and Procedure. Approval conditional upon installation of adequate BOP equipment; description of water source and water rights; and submittal of an approval plan to protect the environment from pollution which might be caused from mud and water impoundment, human waste, and garbage or trash.

Should you determine that it will be necessary to plug and abandon this well, you are hereby requested to immediately notify the following:

RONALD J. FIRTH - Chief Petroleum Engineer

Office: 533-5771 Home: 571-6068

Enclosed please find Form OGC-8-X, which is to be completed whether or not water sands (acquifers) are encountered during drilling. Your cooperation in completing this form will be appreciated.

Further, it is requested that this Division be notified within 24 hours after drilling operations commence, and that the drilling contractor and rig number be identified.

The API number assigned to this well is 43-015-30161.

Sincerely,

Norman C. Stout

Administrative Assistant

NCS/as

cc: State Lands

Enclosure



Scott M. Matheson, Governor Temple A. Reynolds, Executive Director Dr. G. A. (Jim) Shirazi, Division Director

4241 State Office Building • Salt Lake City, UT 84114 • 801-533-5771

December 23, 1983

Pool Energy Corporation 309 Guaranty Bank Bldg. 817-17th Street Denver CO 80202

> Re: Well No. Range Creek #1-16 API #43-015-30161 956' FNL, 538' FWL NW NW Sec. 16, T. 17S, R. 14E. Emery County, Utah

Gentlemen:

In reference to the above mentioned well, considerable time has gone by since approval was obtained from this office.

This office has not received any notification of spudding. If you do not intend to drill this well, please notify this Division. If spudding or any other activity has taken place, please send necessary forms. If you plan to drill this location at a later date, please notify as such.

We will be happy to acknowledge receipt of your response to this notice if you will include an extra copy of the transmittal letter with a place for our signature, and a self addressed envelope for the return. Such acknowledgement should avoid unnecessary mailing of a second notice from our agency.

Your prompt attention to the above will be greatly appreciated.

Respectfully,

Claudia Jones

Well Records Specialist

CJ/ci



January 19, 1984

DIVISION OF OL, GAS & MINING

State of Utah Natural Resources, Oil, Gas & Mining 4241 State Office Building Salt Lake City, Utah 84114

Attention: Ms. Claudia Jones

Re: Well No. Range Creek 1-16 API #43-015-30161 Emery County, Utah

Gentlemen:

With reference to your letter of December 23, 1983, we are enclosing a copy of a letter from the assistant director, State of Utah Natural Resources office, verifying that a two-year extension until May 1, 1985, has been granted on this lease.

The referenced well has been spudded and conductor casing set.

Please contact us if you require any further information.

Very truly yours,

Thomas A. Pool

TAP/mr

Enc.

Scott M. Matheson, Governor Temple A. Reynolds, Executive Director Dr. G. A. (Jim) Shirazi, Division Director

4241 State Office Building • Salt Lake City, UT 84114 • 801-533-5771

January 30, 1984

Thomas Pool 309 Guaranty Bank Building 817 17th St. Denver CO 80202

> RE: Well No.Range Creek #1-16 API #43-015-30161 956' FNL, 538' FWL NW/NW Sec. 16, T. 16S, R. 14E. Emery County, Utah

Dear Sir:

Thankyou for your letter regarding Well No. Range Creek #1-16

In the approval letter sent from this office on March 10 1983 there were several conditions set forth. To date this office has not received a description of the water source and water rights for this well. Also accept this letter as a reminder to submit a copy of the appropriate BOP equipment before you resume drilling.

This office was not notified of the spudding of this well within 24 hours after drilling operations commenced. A spudding report should include the name of the drilling contractor, rig#, and the date, time and method of spudding.

Enclosed is a copy of the approval letter and also several "Sundry Notices" to aid you in compliance with the General Rules and Regulations and Rules and Practice And Procedure.

Your prompt attention to this matter will be appreciated.

Respectfully,

Claudia Jones

Well Records Specialist

CJ/cj enclosures February 14, 1984



DIVISION OF OH, GAS & MINING

State of Utah Natural Resources 4241 State Office Building Salt Lake City, Utah 84114

Attention: Claudia Jones

Well Records Specialist

Re: Range Creek #1-16 Well

Sec. 16, T16S R14E Emery County, Utah

Gentlemen:

We are enclosing Sundry Notice form regarding the above-referenced well which you requested in your letter of January 30, 1984.

If there are any further requirements, please advise.

Very truly yours,

Thomas A. Pool

/mr

Enc.



Scott M. Matheson, Governor Temple A. Reynolds, Executive Director Dianne R. Nielson, Ph.D., Division Director

4241 State Office Building • Salt Lake City, UT 84114 • 801-533-5771

September 26, 1984

Pool Energy Corporation 309 Guaranty Bank Building 817 17th Street Denver, Colorado 80202

Gentlemen:

Re: Well No. Range Creek 1-16, Sec. 16, T. 17S., R. 14E. Emery County, Utah - API #43-015-30161

The above referred to well has been under an operation suspended status for six months or longer. Please inform this office of the current status of this wewll location or what operations are currently being performed on this well. Enclosed is Form OGC-1b, "Sundry Notices and Reports on Wells, that you may use to inform our office regarding this matter.

If operations on this well have been resumed, please submit the appropriate "Sundry Notices" on the drilling operations as stated in rule C-22.

Where the well is in the process of being drilled, said report must be made for each calendar month, beginning with the month in which drilling operations were initiated and must be filed on or before the sixteenth (16) day of the succeeding month.

We have enclosed forms for your convenience in complying with the aforementioned rule.

Thank you for your prompt attention to the above matter.

Claudia Jones

Claudia Jones

Well Records Specialist

clj Enclosure cc: Dianne R. Nielson Ronald J. Firth John R. Baza File 00000006/12

STATE OF UTAH DIVISION OF OIL, GAS AND MINING INSPECTION RECORD

Operator POOL ENERGY	Lease
	Contractor
Well No. RANGE CREEK #1-16	
Location NW NW Sec. 16 T. 17S R. 14E	Operation: Drilling Workover Completion
Field WILDCAT	Abandonment
County EMERY State UTAH	ProducingOther
Individual Well Ins	spection
General:	
Well Sign BOP Pollution Housekeeping Safety Surface u	n control Marker Location
Remarks: A Year ago, Pool Energy set the above mentioned section, as per the file in our well records. The casing as culvert pipe. A lid has been weld ascertain if there was indeed a piece of there are no signs, or identifying writthey had drilled it last summer: 1 year their location. Lease and Facilities I mile from the highway, Fast side of I Facilities inspected: Identification Housekeeping Measurement facilities Storage and handling facilities Remarks:	eir permit, and the configential I waw was corrugated iron such ed over the top, so that I could not of Steel pipe 30 Inches in diameter ting near by. A local farmer said ragoThis location is correct for Inspection
Action:	
Name for Woulfe Title April 5, 1984	Use: V for yes or satisfactory x for no or unsatisfactory NA for not applicable

NA for not applicable



OSET 19 1901

October 17, 1984

State of Utah Natural Resources 4241 State Office Building Salt Lake City, Utah, 84114 Attention: Ms. Claudia Jones

> RE: Range Creek #1-16 Section 16, Township 17S, Range 14E API #43-015-30161

Gentlemen:

In response to your letter dated September 26, 1984, the referenced well remains in its temporarily suspended status.

We are participating in a seismic program presently being shot across the referenced lease area by Sefel Geophysical. We should have results of this seismic investigation with processed data by December 1, 1984, which hopefully will confirm our selected location as the most prospective on the lease.

Pending results of the seismic data, we anticipate resuming operations on the lease in early 1985.

Very truly yours,

Thomas A. Pool

TAP:kr





Norman H. Bangerter, Governor Dee C. Hansen, Executive Director Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

May 2, 1985

Pool Energy Corporation 1600 Stout Street #1010 Denver, Colorado 80202

Gentlemen:

Re: Well No. Range Creek 1-16 - Sec. 16, T. 17S., R. 14E., Emery County, Utah - API #43-015-30161

The above referenced well has been under an operation suspended status for six months or longer. Please inform this office of the current status of this well location or what operations are currently being performed on this well.

Enclosed is Form OGC-lb, "Sundry Notices and Reports on Wells", that you may use to inform our office regarding this matter.

Sincerely,

Pam Kenna

Well Records Specialist

Enclosure
cc: Dianne R. Nielson
Ronald J. Firth
John R. Baza

File

01705/40



Scott M. Matheson, Governor Temple A. Reynolds, Executive Director Ralph A. Miles, Division Director

3100 State Office Building · Salt Lake City, UT 84114 · 801-533-5381

June 15, 1983

Pool Oil & Gas Suite 309, Guaranty Bank Building 817-17th Street Denver, CO 80202

Gentlemen:

This is to advise you that the Director, on May 16, 1983, approved the extension of Oil, Gas, and Hydrocarbon Lease ML 29559 on Section 16, T17S, R14E, SLM., for a period of two years until May 1, 1985. This approval was granted on the basis of your commencement of drilling operations on this lease. It was assumed that you would continue the operations on the lease beyond spudding the well. In fact, we were assured that a larger rig would be moved onto the property as soon as possible. We will continue to monitor the progress of this well.

I trust this will be sufficient for your needs.

Yours very truly,


DONALD G. PRINCE ASSISTANT DIRECTOR

DGP/bp

112-29559 Least had expired and fool Energy is asking for their bond to be released. need and inspector to sheek & see of well is abandoned. below fine St. londs

STATE OF UTAH DIVISION OF OIL, GAS AND MINING OIL AND GAS INSPECTION RECORD

OPERATOR Pool Ene	rgv Corp.	LEASE M	L-29559
WELL NO. Range Cree	k 1-16		15 - 30161
SEC. 16 T. 175 R. 11	1E CONTRACTOR		
CCUNTY _ Em env		deat	
DRILLING/COMPLETION/WORKOVE			
APD SAFETY OPERATIONS	WELL SIGN POLL. CONTROL OTHER	HOUSEKEEPING SURFACE USE	BCPE PITS
SHUT-IN / TA : WELL SIGN 7	✓ HOUSEKEEPING	AA EQUIPMENT*	
ABANDONED: MARKER	HOUSEKEEPING	REHAB.	OTHER
PRODUCTION: WELL SIGN METERING* SECURITY	HOUSEKEEPING POLL. CONTROL SAFETY	EQUIPMENT* PITS OTHER	FACILITIES*
GAS DISPOSITION:VENTED/FLARED	SOLD	LEASE USE	
LEGEND: Y - YES OR SATIS N - NO OR UNSATI NA - NOT APPLICA	ISFACTORY	- 	
*FACILITIES INSPECTED:			
REMARKS: This well has b	peen duillal to	an unknown dep	th as a conducto
pipe of 16" corregated p	ipe has been set	andis unplugged	down to at last
pipe of 16" corregated p 50'. No other casings and abandoned	overe doserved. 1	his well is not x	vopert slugged
CALLY THE TEXT OF THE TAXABLE PARTY.			
ACTION: Need dutling vep	ents leven it only n	et hole ng set ste p	ipe) and needs
INSPECTOR: WM M	,	2	ATE 11-6-85
2.10 CO 1011.	10th	U	HIE II 0 0



Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

January 8, 1986

Pool Energy Corporation 1600 Stout Street #1010 Denver, Colorado 80202

Gentlemen:

Re: Well No. Range Creek 1-16 - Sec. 16, T 17S, R 14E Emery County, Utah - API #43-015-30161

This letter is to advise you that the "Well Completion or Recompletion Report and Log" for the above referenced well is due and has not been filed with this office as required by our rules and regulations.

Please complete the enclosed Form OGC-3, and forward it to this office as soon as possible, but not later than January 20, 1986.

Sincerely

Tami Searing

Well Records Specialist

Enclosure
cc: Dianne R. Nielson
Ronald J. Firth
John R. Baza
File

0320/24

	100 -
To Jean	
	Time 9:00
M Rof Me)	WERE OUT
of	
Phone 303/274	- 4367
TELEPHONED	PLEASE CALL
CALLED TO SEE YOU RETURNED YOUR CALL	WILL CALL AGAIN
CALLING LONG DISTAN	
	ugged the well
lottone, 2.	sacked in middle
	wow top. Course
	Operator

He place and it was cut off. below ground level.







Norman H. Bangerter, Governor Dee C. Hansen, Executive Director Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

August 8, 1986

RETURN RECEIPT REQUESTED P 168 903 941

Pool Energy Corporation 1600 Stout Street, #1010 Denver, Colorado 80202

Gentlemen:

Re: Well No. Range Creek 1-16 - Sec. 16, T. 17S, R. 14E Emery County, Utah - API #43-015-30161

A records review indicates that no required reports for the referenced well have been filed since October 17, 1984 (received telephone information from Rob McMullen on February 3, 1986). Monthly drilling reports must be submitted to account for the time between spudding and well completion.

Rule 312 of the Oil and Gas Conservation General Rules requires that Form DOGM-3 "Well Completion or Recompletion Report and Log " or copy of the equivalent federal form, along with copies of logs and tests run, be filed with this office not later than 90 days after suspending drilling operations and/or plugging procedure.

Please use the address listed below to provide the required information at your earliest convenience, but not later than August 27, 1986.

Utah Division of Oil, Gas and Mining Attention: Suspense File - Norm Stout 355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203

Respectfully,

Norman C. Stout Records Manager

ts

Dianne R. Nielson cc: Ronald J. Firth

John R. Baza

Well File

Suspense File

04485/4

168 903 941



RECEIPT FOR CERTIFIED MAIL

NO INSURANCE COVERAGE PROVIDED NOT FOR INTERNATIONAL MAIL

	(See Reverse)		
Sent to Corp.			
*	Street Pro No. Stout Stree		
410-04-440-0	P.O., State and ZIP Code Denver, Colorado 80202		
5	Postage	\$	
k	Certified Fee	-	
	Special Delivery Fee		
	Restricted Delivery Fee		
	Return Receipt Showing to whom and Date Delivered		•
700	Return receipt showing to whom, Date, and Address of Delivery	É	
	TOTAL Postage and Fees	**** \	
5	Postmark or Date	3	
5		300	
ЭI	**************************************	6994	

UNITED STATES POSTAL SERVICE OFFICIAL BUSINESS

SENDER INSTRUCTIONS (/R Print your name, address, and ZIP Code in the space below.

Complete Items 1, 2, 3, and 4 on the reverse.

Attach to front of article if space permits, otherwise affix to back of article.

 Endorse article "Return Receipt Requested" adjacent to number.



PENALTY FOR PRIVATE USE. \$300



STATE OF UTAH NATURAL RESOURCES

OIL, GAS, & MINING

No SALFTON ECT SUIT FALES 187-1203

(City, State, and ZIP Code)

DIVISION OF OIL, GAS & MINING



Norman H. Bangerter, Governor Dee C. Hansen, Executive Director Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

September 9, 1986

RETURN RECEIPT REQUESTED P 168 903 933

Pool Energy Corporation 1600 Stout Street, #1010 Denver, Colorado 80202 2nd NOTICE

Gentlemen:

Re: Well No. Range Creek 1-16 - Sec. 16, T. 17S, R. 14E Emery County, Utah - API #43-015-30161

A records review indicates that no required reports for the referenced well have been filed since October 17, 1984 (received telephone information from Rob McMullen on February 3, 1986). Monthly drilling reports must be submitted to account for the time between spudding and well completion.

Rule 312 of the Oil and Gas Conservation General Rules requires that Form DOGM-3 "Well Completion or Recompletion Report and Log " or copy of the equivalent federal form, along with copies of logs and tests run, be filed with this office not later than 90 days after suspending drilling operations and/or plugging procedure.

Please use the address listed below to provide the required information at your earliest convenience, but not later than September 30, 1986.

Utah Division of Oil, Gas and Mining Attention: Suspense File - Norm Stout 355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203

Respectfully,

Norman C. Stout Records Manager

ts

cc: Dianne R. Nielson Ronald J. Firth John R. Baza Well File Suspense File

04485/4

EEP EOP 844 9.



RECEIPT FOR CERTIFIED MAIL

NO INSURANCE COVERAGE PROVIDED NOT FOR INTERNATIONAL MAIL

	(See Reverse)		
3-014	Sent to Pool Energy Con	poration	
84-44	Street and No. 1600 Stout Stre		
Sent to Pool Energy Corpora Street and No Stout Street # P.O., State and ZIP Code Denver, Colorado 80 Postage Certified Fee			
.S.G.F	Postage	\$	
*	Certified Fee		
	Special Delivery Fee		
	Restricted Delivery Fee		
	Return Receipt Showing to whom and Date Delivered		
1982	Return receipt showing to whom, Date, and Address of Delivery	~	
PS Form 3800, Feb. 1982	TOTAL Postage and Fees	\$	
3800,	Postmark or Date	£ 7	
orn.			
PS F			

UNITED STATES POSTAL SERVICE OFFICIAL BUSINESS

SENDER INSTRUCTIONS Print your name, address, and ZIP Code in the

Complete items 1, 2, 3, and 4 on the reverse. Attach to front of article if space permits, otherwise affix to back of article. Endorse article "Return Receipt Requested" adjacent to number.







Norm,

Well is PxA. State

Lands has released lease

§ bond. Operator no longer

exists. I think we can

administratively abandon

this well.

IRB

TAMI,

PLEASE COPY JOHN'S NOTE TO

USE FOR ACTION, AND TO PUT

IN FILE.

1NX 5-6-67